

Quarterly Mock Drill Report for the period of July to September 2019

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
Name of Organization: NHPC						
1.	Bairasiul Power Station, Chamba	Himachal Pradesh	Power House	Fire	27.09.2019 at 12.02 hrs	System was working satisfactory.
2.	Bairasiul Power Station, Chamba	Himachal Pradesh	Unit Line	Armed Attack	30.07.2019 at 16.00 hrs	All the functionaries participated in complete coordination and the drill was completed successfully.
3.	Bairasiul Power Station, Chamba	Himachal Pradesh	Main entrance of the Unit BN	Terrorist attack	38.08.2019 at 16.30 hrs	Unit in-charge de-briefed to all force personnel and appreciated the work done by team.
4.	Bairasiul Power Station, Chamba	Himachal Pradesh	Prasasanik Building area.	Bomb Threat	30.09.2019 at 16:30 hrs	Mock drill was completed successfully.
5.	Chamera Power Station-1, Chamba	Himachal Pradesh	Dam	Failure of Power Backup	26.09.2019 at 15:30 hrs.	Mock drill was completed successfully.
6.	Chamera Power Station-1, Chamba	Himachal Pradesh	Switchyard	Failure of back Power	25.07.2019 at 09:40 hrs	Mock drill was completed successfully.
7.	Chamera Power Station-1, Chamba	Himachal Pradesh	Ravi Retreat	Fire	22.08.2019 at 12:00 hrs	Mock drill was completed successfully.
8.	Chamera Power Station-1, Chamba	Himachal Pradesh	Switchyard	Bomb Threat	30.09.2019 at 16:30 hrs	Mock drill was completed successfully.
9.	Chamera Power Station-1, Chamba	Himachal Pradesh	Switchyard	Failure of back Power	26.08.2019 at 15:41 hrs	Mock drill was completed successfully.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
10.	Chamera Power Station-1, Chamba	Himachal Pradesh	Entrance of Unit /bn	Terrorist attack	30.08.2019 at 16:30 hrs	Mock drill was completed successfully.
11.	Chamera Power Station-1, Chamba	Himachal Pradesh	Unit Line CPS-I khairi	Terrorist attack	30.07.2019 at 16:00 hrs	Mock drill was completed successfully.
12.	Chamera Power Station-II, Chamba	Himachal Pradesh	Power Station	Earthquake	11.07.2019 at 12:45 hrs	Mock drill was completed successfully.
13.	Chamera Power Station-II, Chamba	Himachal Pradesh	Power Station	Fire	26.07.2019 at 12:45 hrs	Mock drill was completed successfully.
14.	Chamera Power Station-II, Chamba	Himachal Pradesh	D.G.Set	Failure of backup power	27.07.2019 at 11:50 hrs	Mock drill was completed successfully.
15.	Chamera Power Station-II, Chamba	Himachal Pradesh	Quarter Guard Line CISF	Terrorist Attack	30.07.2019 at 16:00 hrs	Mock drill was completed successfully.
16.	Chamera Power Station-II, Chamba	Himachal Pradesh	DG set	Failure of backup power	30.08.2019 at 15:51 hrs	Mock drill was completed successfully.
17.	Chamera Power Station-II, Chamba	Himachal Pradesh	K.O.Su.Bal Eykaye Gate	Terrorist Attack	30.08.2019 at 16:30 hrs	Mock drill was completed successfully.
18.	Chamera Power Station-II, Chamba	Himachal Pradesh	Baandh Parisar	Fire	10.09.2019 at 15:00 hrs	Mock drill was completed successfully.
19.	Chamera Power Station-II, Chamba	Himachal Pradesh	Baandh Parisar	Failure of backup Power	10.09.2019 at 14:42 hrs	Mock drill was completed successfully.
20.	Chamera Power Station-III, Chamba	Himachal Pradesh	Dam, Khadamukh	Failure of backup Power	15.07.2019 at 13:25 hrs	Mock drill was completed successfully.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
21.	Chamera Power Station-III, Chamba	Himachal Pradesh	CHEP-III Lines Lothal.	Terrorist attack	30.07.2019 at 16:00 hrs	Mock drill was completed successfully.
22..	Chutak Power Station	Jammu and Kashmir	Power House complex	Terrorist attack	19.08.2019 at 11:30 hrs	Mock drill was completed successfully.
23.	Dhauliganga Power Station, Tapovan Pithoragarh	Uttarakhand	DGPS Central Store.	Fire at vital installation.	24.08.2019 at 15:10 hrs	Regular training and awareness to the staff to avoid any fire incident.
24.	Dhauliganga Power Station, Tapovan Pithoragarh	Uttarakhand	DG Room, Tapovan.	Failure of backup Power.	23.07.2019 at 14:30 hrs	Mock drill was completed successfully.
25.	Dhauliganga Power Station, Tapovan Pithoragarh	Uttarakhand	Line area from river side.	Armed attack on Unit line	30.07.2019 at 16:00 hrs	Mock drill was completed successfully.
26.	Dhauliganga Power Station, Tapovan	Uttarakhand	Power House Plant Main gate.	Forcible Armed intrusion	29.08.2019 at 15:30 hrs	Mock drill was completed successfully.
27.	Dhauliganga Power Station, Tapovan Pithoragarh	Uttarakhand	Dam, Chhirkila	Earthquake.	30.09.2019 at 11:30 hrs	Mock drill was completed successfully.
28.	Dhauliganga Power Station, Tapovan Pithoragarh	Uttarakhand	ADM Premises	Armed intrusion of militants.	27.09.2019 at 16:00 hrs	Mock drill was completed successfully.
29.	Dulhasti Power Station	Jammu & Kashmir	Workshop.	Fire	06.07.2019 at 12:00 hrs	Mock drill was completed successfully.
30.	Dulhasti Power Station	Jammu & Kashmir	Dulhasti Power Station(LV Room)	Electrocution.	03.10.2019 at 12:00 hrs	Mock drill was completed successfully
31.	Dulhasti Power Station	Jammu & Kashmir	Shalimar Coy, CISF Dulhasti PS.	Militant in Police Uniform attack threat.	30.08.2019 at 16:30 hrs	Mock drill was completed successfully

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
32.	Dulhasti Power Station	Jammu & Kashmir	Dam site.	Electrocution.	23.07.2019 at 13:00 hrs	Mock drill was completed successfully
33.	Kishanganga Power Station, Bandipora	Jammu and Kashmir	01, NHPC campus	Armed attack	30.07.2019 at 16:00 hrs	Practice classes may be increased to enhance coordination.
34.	Kishanganga Power Station, Bandipora	Jammu and Kashmir	Dam site	Militant in Police uniform attack threat.	30.08.2019 at 16:30 hrs	Practice classes may be increased to enhance coordination.
35.	Kishanganga Power Station, Bandipora	Jammu and Kashmir	01, NHPC campus	Fidayeen attack at rear gate.	30.09.2019 at 16:30 hrs	Practice classes may be increased to enhance coordination.
36.	Loktak Power Station, Churachandpur	Manipur	Transport area NHPC	Accident of the Vehicle.	28.07.2019 at 12:00 hr	Mock drill was completed successfully.
37.	Loktak Power Station, Churachandpur	Manipur	Power House area.	Failure of backup Power	30.07.2019 at 11:00 hrs	Mock drill was completed successfully.
38.	Loktak Power Station, Churachandpur	Manipur	Loktak NHPC campus.	Armed attack	27.07.2019 at 12:00 hrs	Mock drill was completed successfully.
39.	Loktak Power Station, Churachandpur	Manipur	Power house area	Flooding at vital installation.	30.07.2019 at 15:00 hrs	Mock drill was completed successfully.
40.	Loktak Power Station, Churachandpur	Manipur	NHPC campus.	Bomb threat.	02.08.2019 at 11:00 hrs	Mock drill was completed successfully.
41.	Loktak Power Station, Churachandpur	Manipur	Power channel.	Drowning of the Boat.	23.08.2019 at 10:00 hrs	Mock drill was completed successfully.
42.	Loktak Power Station, Churachandpur	Manipur	Power House, LT Room.	Electrocution.	26.08.2019 at 11:00 hrs	Mock drill was completed successfully.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
43.	Loktak Power Station, Churachandpur	Manipur	Power House, canteen area.	Fire.	27.08.2019 at 10:00 hrs	Mock drill was completed successfully.
44.	Loktak Power Station,	Manipur	Power House, canteen area.	Fire.	21.09.2019 at 15:00 hrs	Mock drill was completed successfully.
45.	Loktak Power Station, Churachandpur	Manipur	NHPC campus.	Armed attack.	26.09.2019 at 10:00 hrs	Mock drill was completed successfully.
46.	Loktak Power Station, Churachandpur	Manipur	Power House, area.	Failure of backup Power.	23.09.2019 at 14:00 hrs	Mock drill was completed successfully.
47.	Parbati -II, Nagwain Distt Mandi	Himachal Pradesh	Project Office, PHEP-II	Accident of Vehicle.	16.07.2019 at 16:00 hrs	Mock drill was completed successfully.
48.	Parbati -II, Nagwain Distt Mandi	Himachal Pradesh	Office & Residential complex	Bomb threat	24.07.2019 at 11:30 hrs	Mock drill was completed successfully.
49.	Parbati -II, Nagwain Distt Mandi	Himachal Pradesh	Dam site.	Bomb threat	26.07.2019 at 13:30 hrs	Mock drill was completed successfully.
50.	Parbati -II, Nagwain Distt Mandi	Himachal Pradesh	Power House.	Fire	26.07.2019 at 10:00 hrs	Mock drill was completed successfully.
51.	Parbati -II, Nagwain Distt Mandi	Himachal Pradesh	Dam site.	Bomb threat	17.08.2019 at 13:00 hrs	Mock drill was completed successfully.
52.	Parbati -II, Nagwain Distt Mandi	Himachal Pradesh	Power House.	Bomb threat	14.09.2019 at 12:00 hrs	Mock drill was completed successfully.
53.	Parbati -II, Nagwain Distt Mandi	Himachal Pradesh	Office Complex.	Fire.	30.09.2019 at 10:00 hrs	Mock drill was completed successfully.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
54.	Parbati -III, Behauli, Kullu	Himachal Pradesh	Parbati-III Dam	Failure of backup power	02.08.2019 at 10:40 hrs	Mock drill was completed successfully.
55.	Parbati -III, Behauli, Kullu	Himachal Pradesh	Power House.	Earth quake.	06.08.2019 at 15:50 hrs	Mock drill was completed successfully.
56.	Parbati -III, Behauli, Kullu	Himachal Pradesh	Parbati-III Dam	Failure of backup Power.	20.08.2019 at 09:42 hrs	Mock drill was completed successfully.
57.	Parbati -III, Behauli, Kullu	Himachal Pradesh	Parbati-III Power House.	Fire.	26.08.2019 at 15:10 hrs	Mock drill was completed successfully.
58.	Parbati -III, Behauli ,Kullu	Himachal Pradesh	Parbati-III Dam	Failure of backup Power.	18.09.2019 at 10:55 hrs	Mock drill was completed successfully.
59.	Parbati -III, Behauli, Kullu	Himachal Pradesh	Power House.	Fire	25.09.2019 at 14:45 hrs	Mock drill was completed successfully.
60.	Parbati -III, Behauli, Kullu	Himachal Pradesh	Quarter guard area.	Terrorist attack.	30.07.2019 at 16:00 hrs	Mock drill was completed successfully.
61.	Parbati -III, Behauli, Kullu	Himachal Pradesh	Power House.	Terrorist attack.	30.08.2019 at 16:30 hrs	Mock drill was completed successfully.
62.	Parbati -III, Behauli, Kullu	Himachal Pradesh	Quarter guard area.	Bomb threat.	30.09.2019 at 16:30 hrs	Mock drill was completed successfully.
63.	Rangit Power Station	Sikkim	At Ranjit Dam.	Back-up Power Failure	09.08.2019 at 12:30 hrs	Mock drill was completed successfully.
64.	Rangit Power Station	Sikkim	At Ranjit Dam.	Fire.	03.09.2019 at 11:30 hrs	Mock drill was completed successfully.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
65.	Rangit Power Station	Sikkim	Control Room	Back-up Power Failure	09.07.2019 at 12:33 hrs	Mock drill was completed successfully.
66.	Salal Power Station, Jyotipuram	Jammu & Kashmir	Dam.	Fire.	30.09.2019 at 11.00 hrs	Mock drill was completed successfully.
67.	Salal Power Station, Jyotipuram	Jammu & Kashmir	Admin Building # 2	Earthquake Evacuation drill.	24.09.2019 at 16:30 hrs	Mock drill was completed successfully.
68.	Salal Power Station, Jyotipuram	Jammu & Kashmir	Unit Line, Jyotipuram	Armed Attack	30.07.2019 at 16:00 hrs	Mock drill was completed successfully.
69.	Salal Power Station, Jyotipuram	Jammu & Kashmir	Mandir Chowk Gate.	Armed Attack	30.08.2019 at 16:30 hrs	Mock drill was completed successfully.
70.	Salal Power Station, Jyotipuram	Jammu & Kashmir	Power House Building Primises.	Bomb threat.	30.09.2019 at 16:30 hrs	Mock drill was completed successfully.
71.	Sewa -II Power Station Mashka, Kathua	Jammu & Kashmir	Sewa-II, Mashka.	Failure of Backup Power.	18.07.2019 at 11:45 hrs	Mock drill was completed successfully.
72.	Sewa -II Power Station Mashka, Kathua	Jammu & Kashmir	Sewa-II, Mashka.	Failure of Backup Power.	25.07.2019 at 11:15 hrs	Mock drill was completed successfully.
73.	Sewa -II Power Station Mashka, Kathua	Jammu & Kashmir	Sewa-II, Mashka.	Failure of Backup Power.	03.09.2019 at 11:20 hrs	Mock drill was completed successfully.
74.	Sewa -II Power Station Mashka, Kathua	Jammu & Kashmir	Sewa-II, Mashka Field Hostel.	Fire.	03.09.2019 at 15:10 hrs	Mock drill was completed successfully.
75.	Sewa -II Power Station Mashka, Kathua	Jammu & Kashmir	Sewa-II, Sarthali Dam.	Failure of Backup Power.	06.09.2019 at 11:15 hrs	Mock drill was completed successfully.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
76.	Sewa –II Power Station Mashka, Kathua	Jammu & Kashmir	Plant Area	Failure of Backup Power.	11.09.2019 at 15:15 hrs	Mock drill was completed successfully.
77.	Sewa –II Power Station Mashka, Kathua	Jammu & Kashmir	Sarthali,Sewa-II	Flood at vital installation.	18.09.2019 at 11:35 hrs	Mock drill was completed successfully.
78.	Sewa –II Power Station Mashka, Kathua 18.092019	Jammu & Kashmir	Sarthali-Dam ,	Failure of Backup Power.	18.09.2019 at 11:35 hrs	Mock drill was completed successfully.
79.	Sewa –II Power Station Mashka, Kathua	Jammu & Kashmir	Sarthali	Fire.	21.09.2019 at 15:30 hrs	Mock drill was completed successfully.
80.	Sewa –II Power Station Mashka, Kathua	Jammu & Kashmir	Sewa-II,Mashka.	Failure of Backup Power.	24.09.2019 at 15:30 hrs	Mock drill was completed successfully.
81.	Sewa –II Power Station Mashka, Kathua	Jammu & Kashmir	Sewa-II, Mashka.	Fire.	24.09.2019 at 11:30 hrs	Mock drill was completed successfully.
82.	Sewa –II Power Station Mashka, Kathua	Jammu & Kashmir	Sewa-II,Mashka Power house.	Failure of Backup Power.	27.09.2019 at 15:20 hrs	Mock drill was completed successfully.
83.	Sewa –II Power Station Mashka, Kathua	Jammu & Kashmir		Terrorist attack.	30.07.2019 at 15:15 hrs	Mock drill was completed successfully.
84.	Sewa –II Power Station Mashka, Kathua	Jammu & Kashmir	Main entrance of the unit/Bn	Terrorist attack.	30.08.2019 at 15:15 hrs	Mock drill was completed successfully.
85.	Sewa –II Power Station Mashka, Kathua	Jammu & Kashmir		Bomb Threat.	30.09.2019 at 15:15 hrs	Mock drill was completed successfully.
86.	Tanakpur Power Station, Champawat, Banbassa	Uttarakhand	DPH Barrage	Failure of Power backup.	30.09.2019 at 12:35 hrs	Any action should be taken after proper communication between DPH Barrage and DPH Banbassa.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
87.	Tanakpur Power Station, Champawat, Banbassa	Uttarakhand	Workshop	Fire.	13.08.2019 at 16:34 hrs	Mock drill was completed successfully.
88.	Tanakpur Power Station, Champawat, Banbassa	Uttarakhand	DPH colony.	Failure of Power backup.	13.08.2019 at 15:20 hrs	Any action should be taken after proper communication between DPH Barrage and DPH Banbassa.
89.	Tanakpur Power Station, Champawat, Banbassa	Uttarakhand	Workshop	Accident of vehicle.	04.07.2019 at 15:40 hrs	Mock drill was completed successfully.
90.	Tanakpur Power Station, Champawat, Banbassa	Uttarakhand	Unit Line.	Fire	28.09.2019 at 16:00 hrs	Mock drill was completed successfully.
91.	Teesta-V Power Station, Balutar	Sikkim	Hospital, Balutar.	Fire.	14.08.2019 at 12:00 hrs	Mock drill was completed successfully.
92.	Teesta-V Power Station, Balutar	Sikkim	EMD, Bautar	Failure of power backup	27.08.2019 at 15:10 hrs	Mock drill was completed successfully.
93.	Teesta-V Power Station, Balutar	Sikkim	17 Min Div. Ord Unit, Bardang.	Joint Fire mock drill.	22.08.2019 at 12:00 hrs	Mock drill was completed successfully.
94.	Teesta Low Dam-IV Power Station, Kalijhora, Darjeeling	West Bengal	Administrative Building.	Fire.	19.07.2019 at 14:20 hrs	Mock drill was completed successfully.
95.	Teesta Low Dam-IV Power Station, Kalijhora, Darjeeling	West Bengal	TLD-IV PS	Failure of backup Power	29.07.2019 at 12:10 hrs	Mock drill was completed successfully.
96.	Teesta Low Dam-IV Power Station Kalijhora, Darjeeling	West Bengal	TLD-IV PS	Flood	27.07.2019 at 11:12 hrs	Mock drill was completed successfully.
97.	Teesta Low Dam-IV Power Station Kalijhora, Darjeeling	West Bengal	TLD-IV PS	Failure of backup Power	03.08.2019 at 11:00 hrs	Mock drill was completed successfully.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
98.	Teesta Low Dam-IV Power Station Kalijhora, Darjeeling	West Bengal	Administrative Building site.	Accident of vehicle	03.08.2019 at 11:33 hrs	Mock drill was completed successfully.
99.	Teesta Low Dam-IV Power Station Kalijhora, Darjeeling	West Bengal	TLD-IV PS	Electrocution.	07.08.2019 at 12:05 hrs	Mock drill was completed successfully.
100.	Teesta Low Dam-IV Power Station Kalijhora, Darjeeling	West Bengal	TLD-IV PS	Failure of backup Power	23.09.2019 at 11:15 hrs	Mock drill was completed successfully.
101.	Teesta Low Dam-IV Power Station Kalijhora, Darjeeling	West Bengal	Power House assembly area.	Fire	26.09.2019 at 12:45 hrs	Mock drill was completed successfully.
102.	Teesta Low Dam-IV Power Station Kalijhora, Darjeeling	West Bengal	Quarter Guard.	Armed attack.	09.07.2019 at 16:00 hrs	Mock drill was completed successfully.
103.	TLD-III Power Station Rambhi, Darjeeling	West Bengal	Store complex	Accident of vehicle.	17.07.2019 at 12:10 hrs	Mock drill was completed successfully.
104.	TLD-III Power Station Rambhi, Darjeeling	West Bengal	Power house control Room.	Failure of backup power.	17.07.2019 at 16:29 hrs	Mock drill was completed successfully.
105.	TLD-III Power Station Rambhi, Darjeeling	West Bengal	Near Barrage control Room.	Failure of backup power.	27.08.2019 at 16:30 hrs	Mock drill was completed successfully
106.	TLD-III Power Station Rambhi, Darjeeling	West Bengal	CISF duty post dam gate-II area.	Armed attack	22.07.2019	Mock drill was completed successfully
107.	TLD-III Power Station Rambhi, Darjeeling	West Bengal	CISF duty post store complex gate area.	Armed attack	21.08.2019 at 16:35 hrs	Mock drill was completed successfully

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
108.	TLD-III Power Station Rambhi, Darjeeling	West Bengal	CISF duty post store complex gate area.	Armed attack	23.09.2019 at 16:35 hrs	Mock drill was completed successfully
109.	Uri - I Power Station, Mohura, Baramulla	Jammu & Kashmir	Canteen at Boniyar.	Vehicle accident.	23.09.2019 at 10:45 hrs	Mock drill was completed successfully.
110.	Uri - I Power Station, Mohura, Baramulla	Jammu & Kashmir	Store and transport complex Boniyar.	Fire	23.09.2019 at 11:45 hrs	Mock drill was completed successfully.
111.	Uri - I Power Station, Mohura, Baramulla	Jammu & Kashmir	Barrage control Room.	Power Backup Failure.	23.09.2019 at 11:45 hrs	Mock drill was completed successfully.
112.	Uri - I Power Station, Mohura, Baramulla	Jammu & Kashmir	Colony area.	Militant in police uniform attack threat.	30.08.2019 at 16:30 hrs	Mock drill was completed successfully.
113.	Uri - I Power Station, Mohura, Baramulla	Jammu & Kashmir	CP Gate.	Hit and run attack.	30.09.2019 at 16:30 hrs	Mock drill was completed successfully.
114.	Uri - I Power Station, Mohura, Baramulla	Jammu & Kashmir	Dam approach gate area.	Power backup failure.	23.09.2019 at 16:30 hrs.	Mock drill was completed successfully.
115.	Uri - II Power Station, Mohura, Baramulla	Jammu & Kashmir	CISF Main Office.	Terrorist attack.	30.07.2019 at 16:00 hrs	Mock drill was completed successfully.
116.	Uri - II Power Station, Mohura, Baramulla	Jammu & Kashmir	Diesel Pump area.	Fire	20.09.2019 at 11:10 hrs	Mock drill was completed successfully.
117.	Uri - II Power Station, Mohura, Baramulla	Jammu & Kashmir	Nursery School.	Fire	23.09.2019 at 13:15 hrs	Mock drill was completed successfully.
118.	Uri - II Power Station, Mohura, Baramulla	Jammu & Kashmir	Administrative Building.	Vehicle accident.	24.09.2019 at 10:30 hrs	Mock drill was completed successfully.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
119.	Uri - II Power Station, Mohura, Baramulla	Jammu & Kashmir	Administrative Building.	Electric shock.	24.09.2019 at 15:30 hrs	Mock drill was completed successfully.
Name of the Plant: Damodar Valley Corporation						
120.	Bokaro Thermal Power station	Jharkhand	Bokaro Thermal	Fire Call	15.07.2019	All the functionaries participated in complete coordination and the drill was completed successfully.
121.	Bokaro Thermal Power station	Jharkhand	Bokaro Thermal	Attack by anti-social elements	25.07.2019	All the functionaries participated in complete coordination and the drill was completed successfully.
122.	Bokaro Thermal Power station	Jharkhand	Bokaro Thermal	Fire call	29.07.2019	All the functionaries participated in complete coordination and the drill was completed successfully.
123.	Bokaro Thermal Power station	Jharkhand	Bokaro Thermal	Fire Call	14.08.2019	All the functionaries participated in complete coordination and the drill was completed successfully.
124.	Bokaro Thermal Power station	Jharkhand	Bokaro Thermal	Attack by Anti-social elements.	24.08.2019	All the functionaries participated in complete coordination and the drill was completed successfully.
125.	Bokaro Thermal Power station	Jharkhand	Bokaro Thermal	Fire call	23.08.2019	All the functionaries participated in complete coordination and the drill was completed successfully.
126.	Bokaro Thermal Power station	Jharkhand	Bokaro Thermal	Fire Call	13.09.2019	All the functionaries participated in complete coordination and the drill was completed successfully.
127.	Bokaro Thermal Power station	Jharkhand	Bokaro Thermal	Fire Call	28.09.2019	All the functionaries participated in complete coordination and the drill was completed successfully.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
128.	Bokaro Thermal Power station	Jharkhand	Bokaro Thermal	Anti-social element attack	30.09.2019	All the functionaries participated in complete coordination and the drill was completed successfully.
Name of Organization: <u>NHDC LTD</u>						
129.	Indira Sagar Power Station, Narmada Nagar	Madhya Pradesh	Parking Area near Access Tunnel	Fire	05.08.2019 at 12:35 hrs	Mock Drill of different nature to be carried out next time.
130.	Omkareshwar Power Station, Khandwa	Madhya Pradesh	Power House	Fire	28.09.2019 at 16.45 hrs	Mock drill was completed successfully.
Name of Organization: <u>Telangana State Power Generation Corporation ltd</u>						
131.	K.T.P.S(O&M), Paloncha Khammam	Telangana	In front of O/o DE/General-'A'	Fire	28.09.2019 at 10:30 hrs	Mock drill was completed successfully.
132.	RTS-B, Ramagundam	Telangana	Near ESP.	Fire	30.09.2019 at 16.00 hrs.	Mock Drill was conducted satisfactorily.
Name of Organization: <u>GVK Jegurupadu Combined Cycle Power Plant, Andhra Pradesh</u>						
133.	GVK Combined Cycle Power Plant, Jegurupadu	<u>Andhra Pradesh</u>	Switch gear Building at BOP of Phase # 2	Electrical Fire In CT Fan #2 Module.	30.07.2019 at 15.58 hrs.	Mock Drill was conducted satisfactorily.
134.	Godavari Gas Power Plant, Jegurupadu	<u>Andhra Pradesh</u>	H2So4 Storage Tank-2 of Phase-I	Sulphuric Acid Leak	25.07.2019 at 11.45 hrs.	Mock Drill was conducted satisfactorily.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
135.	Godavari Gas Power Plant, Jegurupadu	<u>Andhra Pradesh</u>	Open Cycle Switch Gear Cable Gallary at GGPP	Smoke	25.09.2019 at 16.06 hrs.	Mock Drill was conducted satisfactorily.
Name of Organization: <u>The West Bengal Power Development Corporation Limited</u>						
136.	Sagardighi Thermal Power Project	West Bengal	Stg.II-#4 ESP-Trafo-Rectifier	Fire.	14.09.2019 at 16:12 hrs	Such drills should be done at all hazardous operation.
137.	Bandel Thermal Power Station.	West Bengal	Assembly Point 2	Fire in garbage	19.07.2019 at 16:15 hrs	This should be discussed in training class and HOD meeting for awareness about proper communication and extinguishing operation.
138.	Bakreswar Thermal Power Project	West Bengal	In front of Administrative Building.	Fire	19.07.2019 at 11:30 hrs	All unwanted materials shall have to be shifted to scrap yard.
139.	Santaldih Thermal Power Project	West Bengal	Chlorination Plant.	Chlorine Leakage.	02.09.2019 at 16:30 hrs	Mock Drill was conducted satisfactorily.
Name of Organization: <u>CESC Limited</u>						
140.	HRD Training Hall.	West Bengal	Training Hall.	Exercise on Disaster Management for Officer.	02.08.2019	Mock Drill was conducted satisfactorily
141.	HRD Training Hall.	West Bengal	Training Hall.	Disaster Management	03.07.2019 06.08.2019 13.09.2019	Mock Drill was conducted satisfactorily
142.	HRD Training Hall.	West Bengal	Training Hall.	Disaster Management	06.07.2019 03.08.2019	Mock Drill was conducted satisfactorily

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
				Workmen	21.09.2019	
143.	Budge Budge generating Station	West Bengal	West side of Coal Office.	Fire.	14.08.2019 at 15:12 hrs	Performance of the Emergency response was found satisfactory.
144.	Southern Generating Station	West Bengal	Crusher House at FHP.	Fire.	21.09.2019	Mock Drill was conducted satisfactorily
145.	Southern Generating Station	West Bengal	Near southern Distribution station.	Intrusion of armed men	21.09.2019 at 16:00 hrs	Mock Drill was conducted satisfactorily
146.	Titagarh Generating Station	West Bengal	TRS Building.	Fire.	11.09.2019 at 16:00 hrs	Mock Drill was conducted satisfactorily
147.	CESC Hose, Corporate Office Building.	West Bengal	CESC House.	Evaluate Preparedness of outsourced Security Person	20.09.2019 at 16:00 hrs	Mock drills on crowd management need to practiced regularly to reduce total reaction time.
148.	CESC Transmission Project Department.	West Bengal	Engineering Office at Poddar Court	Simulation of 3 Nos 220Kv ERS Towers.	09.07.2019	Mock Drill was conducted satisfactorily
149.	CESC Transmission Project Department.	West Bengal	ERS storage Yard–Hi-Tech system.	Use of Critical Tools of ERS	20.09.2019	Mock Drill was conducted satisfactorily
150.	CESC Transmission Project Department.	West Bengal	T&P Go-down Patulia s.stn.	Portable inflatable Tower Lights.	11.09.2019	Mock Drill was conducted satisfactorily
151.	M/s Karam, sector-V,salt lake.	West Bengal	Class Room	Working at Height Awareness.	28.08.2019	Mock drill for these tower lights are being done quarterly.
152.	CESC Stores Kustiya.	West Bengal	Project Site	Fire Drill	31.08.2019	Mock Drill was conducted satisfactorily

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
153.	Titagarh Receiving Station	West Bengal	Project Site	Fire Drill	25.07.2019	Mock Drill was conducted satisfactorily
154.	East Calcutta Sub Station	West Bengal	Project Site	Fire Drill	23.07.2019	Mock Drill was conducted satisfactorily
155	Testing Department.	West Bengal	Project Site	Fire Drill	11.07.2019	Mock Drill was conducted satisfactorily
156.	Botanical Garden.	West Bengal	Project Site	Fire Drill	23.07.2019	Mock Drill was conducted satisfactorily
157.	Mulajore Sub Station	West Bengal	Project Site	Fire Drill	06.08.2019	Mock Drill was conducted satisfactorily
158.	New Cossipore Sub Station	West Bengal	Project Site	Fire Drill	16.08.2019	Mock Drill was conducted satisfactorily
159.	Southern Receiving Station	West Bengal	Project Site	Fire Drill	28.08.2019	Mock Drill was conducted satisfactorily
160.	B.T. Road Switching Station.	West Bengal	Project Site	Fire Drill	03.09.2019	Mock Drill was conducted satisfactorily
161.	Field training regarding operation of Fire Hydrant system	West Bengal	Rear side of Main store. BBGS	Operation of fire Hose and nozzle.	28.08.2019	Mock Drill was conducted satisfactorily
162.	Training for Security staff.	West Bengal	PTC-BBGS	Security matters and intelligence.	16.07.2019 to 28.08.2019	Mock Drill was conducted satisfactorily
163.	Training for Security staff.	West Bengal	PTC-BBGS	Security matters and Firefighting.	23.09.2019	Mock Drill was conducted satisfactorily

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
164.	Fire safety .Use of Fire extinguishers and Water Hydrant System.	West Bengal	PTC-BBGS	Outside lobby	18.07.2019	Mock Drill was conducted satisfactorily
165.	Demonstration and Use of Fire Extinguishers.	West Bengal	PTC-BBGS	Outside lobby	07.08.2019	Mock Drill was conducted satisfactorily
166.	Training on Security	West Bengal	Dist Station Building.	Training	21.09.2019	Mock Drill was conducted satisfactorily
167.	Emergency preparedness in electrical isolation and restoration.	West Bengal	PTC-BBGS	Electrical isolation and restoration.	06.08.2019	Mock Drill was conducted satisfactorily
168.	Training on Fire Safety, Use of Firefighting equipment.	West Bengal	PTC-BBGS	Fire Safety	19.08.2019	Mock Drill was conducted satisfactorily
169.	Training on On-site Emergency Plan.	West Bengal	PTC-BBGS		28.08.2019	Mock Drill was conducted satisfactorily
Name of Organization: Torrent Power Limited						
170.	Torrent Power Limited, Sabarmati, Ahmedabad	Gujarat	Ash pond No2	Evacuate a dead body of anonymous person from ash pond.	26.09.2019 at 16:17 hrs	Mock Drill was conducted satisfactorily
Name of Organization: Power System Operation Corporation Limited.						
171.	Balimela Hydro Power Station,OHPC	Odisha	Balimela Substation	Network Configuration.	17.07.2019 at 11:40 hrs.	In future effort may also be made to form island with a distant load like Jeynagar or Theruvali in place of using the local load at balimela HPS.

Sl. No	Name of Establishment	State	Location	Scenario	Date & Time	Observations/Recommendation /Suggestions/ Activity performed
172.	U.Kolab Power House,OHPC	Odisha	U.Kolab HPS,Bariniput.	Network Configuration.	19.07.2019 at 11:05 hrs.	Mock Drill was conducted satisfactorily
173.	Burla Power House	Odisha	Burla HP,Orissa	Black Start	20.07.2019 at 11:08 hrs	Mock Drill was conducted satisfactorily
174.	Subernrekha HPS	Jharkhand	Subernrekha HPS,Sikidiri	Black start	20.08.2019 at 10:50 hrs.	Mock Drill was conducted satisfactorily
175.	Western System Operation Corporation Limited,Mumbai.	Maharashtra	Parking area near AC Plant	Operation of Fire Fighting System.	05.08.2019 at 16:00 hrs.	Mock Drill was conducted satisfactorily
Name of Organization: Gujarat Industries Power Company Limited.						
176.	Gujarat Industries Power Company Limited.	Gujarat	Service Building.	Fire	12.07.2019 at 15:00 hrs.	Mock Drill was conducted satisfactorily
177.	Gujarat Industries Power Company Limited.	Gujarat	Station transformer. (Unit-2)	Fire	19.08.2019 at 10:30 hrs.	Mock Drill was conducted satisfactorily
178.	Gujarat Industries Power Company Limited.	Gujarat	Station transformer. (Unit-2)	Fire	04.09.2019 at 10:05 hrs.	Mock Drill was conducted satisfactorily
